ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M03245 Client: Alaskan Copper Works Date Received: 11/06/08 Project: PO M03245, F&BI 811056 Date Extracted: 11/10/08 Lab ID: 811056-01 x10 Date Analyzed: 11/11/08 Data File: 811056-01 x10.045

Matrix: Water Instrument: ICPMS1

Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 99 60 125

Concentration ug/L (ppb)

Chromium 480
Nickel 591
Copper 592
Zinc 70.3

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

% Recovery:

<2

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 11/10/08
Date Analyzed: 11/11/08
Matrix: Water
Units: ug/L (ppb)

Internal Standard:

Zinc

Client: Alaskan Copper Works
Project: PO M03245, F&BI 811056
Lab ID: I8-422 mb
Data File: I8-422 mb.039
Instrument: ICPMS1
Operator: hr

Upper Limit:

125

Lower

Limit:

60

Germanium 102

Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1

ENVIRONMENTAL CHEMISTS

Date of Report: 11/13/08 Date Received: 11/06/08

Project: Metro Self Monitor, PO M03245, F&BI 811056

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 811074-14 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria	
Chromium	ug/L (ppb)	<1	<1	nm	0-20	
Nickel	ug/L (ppb)	4.50	4.62	3	0-20	
Copper	ug/L (ppb)	1.12	1.25	11 34	0-20	
Zinc	ug/L (ppb)	10.9	10.6	3	0-20	

Laboratory Code: 811074-14 (Matrix Spike)

			Percent									
Analyte	Reporting Units	Spike Level	Sample Result	Recovery MS	Acceptance Criteria							
Chromium	ug/L (ppb)	20	<1	108	50-150							
Nickel	ug/L (ppb)	20	4.50	102 b	50-150							
Copper	ug/L (ppb)	20	1.12	102	50-150							
Zinc	ug/L (ppb)	50	10.9	100 b	50-150							

Laboratory Code: Laboratory Control Sample

		Spike	Percent Recovery	Acceptance
Analyte	Reporting Units	Level	LCS	Criteria
Chromium	ug/L (ppb)	20	115	70-130
Nickel	ug/L (ppb)	20	129	70-130
Copper	ug/L (ppb)	20	111	70-130
Zinc	ug/L (ppb)	50	98	70-130

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

(96)						· *				# #						» •
FORMS ACCORDED TO	FW. (200) 184-5282	Sentale, WA 88119-2029	3012 16th Avenue West	Property de Brown, Inc.							*	m03245	Sample ID		City, Shake, ZIP SEATTLE CLA 98734 Phome # 206-571 607 Fax # 26-782-4509	SINOS 628 S.
į	A parsminant	To proper to	1									0	Lab ID		THE CLA 60TF Pax # 206	Languer C
	U :	Me Il		STATE OF STA	2							1/6/08) Date		6-782-4509 6-782-4509	& SU
	0	27										12:45	Time			
	* 3	14	T'E)	•							120	Sample Type		REMARKS	PROJECT NAME/NO. PROJECT NAME/NO. Comp Comp
		~ 0	ZENGED TI	LATEL								/	# of containers			AMPANAS GAMENO. METRO SELS Comp
			Corps	BININ					e e e e e e e e e e e e e e e e e e e	Singular Sept.	4-1		TPH-Diesel	H		monder
		My	8							(Junior 100 and	entens un en pad		TPH-Gasoline			4
	7	1	(-				BTEX by 8021B			3
		D							ori Verino				VOCs by 8260	A		U
		`				-		-				No.	SVOCs by 8270	MA		3
		177	\$		-	+	-		-				HFS	YSE		mo32%
S		A,	6	ANVAIMO		-			-			Z	ER CU NEZA	ANALYSES REQUESTED		PO# MO32%
		1	Ç	PA					4-	-				QUI		
7		/]		Y		4						· · ·	A	SIT		1 30 X C
										يخصين	Harperis ex	<u> </u>	<u> </u>	ď	Disp Will	TOR TOR Standau STRUSH
Samples received at	ابت ا		//		· vous-mik lineau										MAMI 988 8 7m 88	
	. [,	de	BLYC											SAMPLE DISPOR Dispose after 30 days Return samples Will call with instruct	TURNAROUND TURNAROUND Standard (2 Weeks) Rush charges suthern
7)	9					l.					-		instr	134章
ငိ			2,20pm	COVILL	· (4)	2 P					. S		Notes		SAMPLE DISPOSAL Dispose after 30 days Return samples Will call with instructions	TURNAROUND TIME TURNAROUND TIME Rush charges suthorized by:

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

November 13, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on November 6, 2008 from the Metro Self Monitor, PO M03245, F&BI 811056 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1113R.DOC